

Cofe PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Pate	nt of:)	
TAKAKAZU TANAKA ET AL.		:	Examiner: Janis L. Dote
Appln. No.: 10/649,679		:	Group Art Unit: 1756
Filed: A	ugust 28, 2003	:	
For:	ELECTROPHOTOGRAPHIC PHOTOSENSITIVE MEMBER, PROCESS CARTRIDGE AND ELECTROPHOTOGRAPHIC APPARATUS	:) :) :	JUN 3 0 2006 of Correction
U.S. Pate	nt No.: 6,994,941 B2	:	•
Issued:	February 7, 2006)	June 2, 2006
Commiss	ioner for Patents		

LETTER CALLING ATTENTION TO ERRORS IN PATENT

Sir:

P.O. Box 1450

Alexandria, VA 22313-1450

The following minor errors have been noted in the above-mentioned

patent:

COLUMN 1

Line 20, "Form" should read --From--; and

Line 27, "member" should read --members--.

COLUMN 3

Line 3, "have" should read --has--.

COLUMN 55

Line 24, "higher" should read --more highly--.

COLUMN 56

Line 63, "dibenzpirene" should read --dibenzpyrene--.

COLUMN 62

Line 65, "dimethoxymehtane" should read --dimethoxymethane--.

COLUMN 63

Line 36, "scratch" should read --scratched--.

COLUMN 73

Table 1, "scratch images" should read --scratched images--.

COLUMN 83

Line 37, "of" should be deleted.

These errors appear to be relatively insignificant and, therefore, have not been included in the Certificate of Correction which has been filed separately. However, it is requested that this paper be placed in the filewrapper of the above-identified patent.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Peter Saxon

Attorney for Patentees Registration No. 24,947

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801

Facsimile: (212) 218-2200



In re Patent of:)	
		:	Examiner: Janis L. Dote
TAKAKAZU TANAKA ET AL.)	
		:	Group Art Unit: 1756
Appln. No.: 10/649,679)	
Tiled. A.		:	
riied: A	ugust 28, 2003)	
For:	ELECTROPHOTOGRAPHIC		
	PHOTOSENSITIVE MEMBER,	:	
	PROCESS CARTRIDGE AND)	
	ELECTROPHOTOGRAPHIC	:	
	APPARATUS)	
		:	
U.S. Patent No.: 6,994,941 B2)	
		:	
Issued:	February 7, 2006)	June 2, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Peter Saxon

Attorney for Patentees Registration No. 24,947

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

Facsimile: (212) 218-2200

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 1 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"00-206721" should read --2000-206721--; and "01-133994" should read --2001-133994--.

ON COVER PAGE AT (56) OTHER PUBLICATIONS

After "Peter Strohreigl et al.,": "phrnylrmnrsminr)," should read --phenyleneamine),--.

COLUMN 17

CT-11,

should read

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile



CERTIFICATE OF CORRECTION

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 2 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile



CERTIFICATE OF CORRECTION

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 3 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21

CT-18,

"
$$CH_3$$
 H_3C
 H_3C
 H_3C
 H_3C
 CH_3
 CH_3
 CH_3

should read

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,994,941 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 4 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 25

CT-12,

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,994,941 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page





PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 5 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

should read

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile



CERTIFICATE OF CORRECTION

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 6 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 43

CT-56,

should read

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

CERTIFICATE OF CORRECTION

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 7 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

$$H_3C$$
 CH_3
 F
 H_3C
 CH_3
 H_3C
 CH_3

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile



PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 8 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 67

CT-17A, "-continued

' should read

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile



PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 1 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"00-206721" should read --2000-206721--; and "01-133994" should read --2001-133994--.

ON COVER PAGE AT (56) OTHER PUBLICATIONS

After "Peter Strohreigl et al.,": "phrnylrmnrsminr)," should read --phenyleneamine),--.

COLUMN 17

CT-11,

"
$$CH_3$$
 H_3C
 H_3C
 H_3C
 H_3C
 CH_3
 CH_3

should read

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,994,941 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 2 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile



CERTIFICATE OF CORRECTION

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 3 of 8

,,

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21

CT-18,

"
$$CH_3$$
 CH_3
 CH_3

should read

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile



PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 4 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 25

CT-12,

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile



PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 5 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

should read

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile



PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 6 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 43

should read

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,994,941 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S)

TAKAKAZU TANAKA ET AL.

Page 7 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

$$- \underbrace{\hspace{1cm} \begin{array}{c} F \\ N \\ N \end{array}} \underbrace{\hspace{1cm} \begin{array}{c} F \\$$

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,994,941 B2

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

PATENT NO.

6,994,941 B2

DATED

February 7, 2006

INVENTOR(S) :

TAKAKAZU TANAKA ET AL.

Page 8 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 67

CT-17A, "-continued

should read

-continued

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,994,941 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

